POPPLETON HISTORIC STUDY

B-21155

Block

Lot

Address

169

16

226 N. Carrollton Avenue MAGI#042155560

Approximate age

1800-1845

1845-1860

1880-1896

1896-on


A cluster of buildings appears on this site on Sachse air view, 1869.

Rating	ating Architectural		Condition		
A	Significant-save	good	fair	poor	bad
\bigcirc B	Quality Indiv./groups-save	good	fair	poor	bad
C	Important to street/groups	good	fair	poor	bad
D	Insignificant/detrimental	good	fair	noor	had

Notable features:


This may well be the old school building, to which various improvements have been added in the course of time. Standing adjacent to St. Luke's Clergy House and the nice building at 215 N. Carrollton, it and the space around it (now used for parking). reduce the density of the neighborhood and compose a pleasant grouping of buildings. Its 12/12 windows do not appear to be vandalized. The smoke stack should be painted white, or a bright color.

Environmental context: The relation to the Clergy House could be improved by planting a group of trees near Rankin Place, and the asphalt setback on Carrollton needs design and planting. If the use is to continue as administrative offices, a redesign of the grounds should take place forthwith, both east and west sides of the building.



Public School No. 15 (Junior High School No. 1031, Colored) 226 N. Carrollton Avenue

Baltimore City



Demolished

B-2455 226 N. Carrollton Avenue Block 0169 Lot 016 Baltimore City Baltimore West Quad.

